	Approved For Re	elease 2002/08 <u>/</u> 21 : CIA-RDP89B005	69R0002000500	93-6
date	1559Z 1Ø DEC 62	TO PIER SECRET	2	Comments of the control of the contr
Dr. a			31	6
B.T. in Alle Communication of personal law of trader	r ogsvensky promise nations i skrige i sky mod skolony. Hodisky skyllogisky krigelyken om och skyllogisky skyl			A CONTROL OF THE CONT
70 :	DIRECTOR			
FROM :	25X1A		The second secon	as two control of the
ACTION	OSA (1-2-3-4-5-6-7-	OPERATIONAL MAMEDIATE		
info :	s/c (16)		The second secon	Control of the Contro
	TOR: 1652Z 10 DEC		IN 5 ⁸ 737	
<u> </u>	5X1A		de scrippe falle einfalle de gegenheide – wird kommen werden werden zu is in de schalle de gegenheide de gesch De falle in 15 mehr de gebruik der de geschiede falle in de geschiede de gegenheide de gegenheide de gegenheide	
£O.		MFO	20 g 1	Ø2Ø6
	25	X1A		25X1A
F	FOR COL LEDFORD FROM			

CHASSISISM MESSANCE

- 1. MSN 3203 WAS EXECUTED ACCORDING TO PLAN WITH ALL TAKE-OFFS ON TIME AND SORTIES FLOWN AS BRIEFED. THE WEATHER IN THE AREA OF INTEREST WAS VERY CLOSE TO PREDICTED WITH REGARD TO CLOUD COVER BUT THE WIND INFO WAS INACCURATE AND ESTIMATE FORECAST FORECAST VELOCITIES AT LEAST 30K HIGH. THIS PRESENTED NO SERIOUS PROBLEM EXCEPT FOR TIME GAINED AND LOST IN THIS AREA AND SLIGHT DRIFT FROM TRACK AT ONE POINT WHILE ABOVE OVERCAST.
- 2. MINOR UHF RECEPTION PROBLEMS WERE ENCOUNTERED BETWEEN TANKER AND RECEIVER DURING RENDEZVOUS AS IF FREQ WAS BEING JAMMED, HOWEVER, BELIEVE IF THIS WAS THE CASE IT WAS ACCIDENTAL. AT ANY RATE FREQ WILL BE CHANGED FOR THE NEXT SORTIE. IN SPITE OF THIS SMALL PROBLEM THIS WAS ONE OF THE FASTEST HOOK-UPS AND FUEL TRANSFERS ACCOMPLISHED TO DATE. TOTAL TIME FROM POINT AIRCRAFT WERE SIDE BY SIDE IN RENDEZVOUS TO START CLIMB BY ARTICLE AFTER REFUELING WAS APPROX 5 MIN. A VERY PROFESSIONAL JOB BY BOTH TANKER AND RECEIVER

TOPSECRET

COMP Control C

Approved For Release 2	2002/08/21 : CIA-RDP89B00569R000200050093-6
25X1A	TOPSECRET
0206 (IN 58737)	PAGE TWO
TEAM WITH REFUELING COMPLETE	APPROX 15 NM PRIOR TO REACHING
25X6 25X1	A
3. AM VIEWING THE	TAKE WITH THE PI AT THIS TIME AND IT
LOOKS GOOD. ALTHOUGH PI WOR	K NOT COMPLETED WE BELIEVE COVERAGE
PRETTY ACCURATELY REFLECTED	IN AT THIS POINT CONSIDER
IT A GOOD MISSION WITH GOOD	COVERAGE EXCEPT FOR AREAS FORECAST
WITH CLOUD COVER AND POSSIBL	Y WEATHER SLIGHTLY BETTER THAN BRIEFED.
25Χ1Δ	E FUEL PRESSURE PROBLEM DISCUSSED
	LIEVE THE SOLUTION IS VERY SIMPLE
	T SUPERVISOR THINKS THAT REMOVAL OF
THE 200 MESH SCREEN WILL ELI	MINATE THE DIFFICULTY WITHOUT DANGER OF
OTHER INDUCED PROBLEMS FROM	THIS ACTION. WOULD APPRECIATE YOUR
ASSISTANCE IN THIS MATTER.	
5. WE ARE IN GOOD SHAPE	AND WILL BE READY TO GO AGAIN EARLY
MORNING OF 12 DEC PROVIDED	EVERYONE IS IN AGREEMENT ON REMOVAL OF
200 MESH SCREEN. OTHERWISE	RECOMMEND NO FURTHER FLIGHTS BE MADE UNTIL
ADEQUATE SOLUTION HAS BEEN F	REACHED.

END OF MESSAGE

SECRET